


U04 ARM / SL735

INSTALLATION INSTRUCTIONS

! WARNING: TO AVOID FIRE, SHOCK OR DEATH, TURN OFF AND LOCKOUT POWER BEFORE PERFORMING ANY MAINTENANCE.

! CAUTION: THIS FIXTURE MUST BE WIRED IN ACCORDANCE WITH THE NATIONAL ELECTRIC CODE AND ALL APPLICABLE LOCAL CODES. PROPER GROUNDING IS REQUIRED. ALL WORK SHOULD BE DONE BY A QUALIFIED ELECTRICIAN.

1. Slide the arm over the pole tenon and secure with set screws. Use the set screws to level and align arm with pole.
2. Hang the fixture from the alignment ball inside the EZ Hang adapter. Be sure to align the fixture front to the arm as shown.
3. Connect arm supply wires to fixture wires. Locate splices in adapter.
4. Attach adapter cover with the two screws provided.
5. Level bottom of fixture. Secure in place by tightening the set screw located in the EZ Hang adapter.



SternbergLighting

ESTABLISHED 1923 / EMPLOYEE OWNED

800-621-3376
555 Lawrence Ave., Roselle, IL 60172
info@sternberglighting.com
www.sternberglighting.com